Declassified in Part - Sanitized Copy Approved for Release 2013/06/25 : CIA-RDP91-01355R000300170008-1 REQUEST FOR DATA/VOICE SERVICE 1. Complete a separate form for each Secure Voice And ADP Service requested. CUSTOMER REQ. Nº C 09746 2. Multiple actions may be requested for Non-Secure Voice Service per form. SECTION 1: Requesting Office Information Date of Request Pril 27, 1988 Directorate/Office/Group/Div DDS&T/FBIS/ESG/HED Requesting Officer _ Phone Blk Bldg/Room RCC-B 3S12 Contact Name _ Renovation YES Yes/No OIT Project No.-OL Project No., Acres 1888 Company Date ___ ADP Approving Official STAT From: Bldg Location of Work Room_SEE-ATTAHCED-MEMO To: Bldg Voice Service Requested SECTION 2 SECTION 3 Secure Non-Secure Quantity Quantity-Now, New Relocate Relocate Modify 1 Modify * :: Disconnect Disconnect Other Other - Type * For eg., telephone numbér change. * For eg., telephone number change. Section 4: ADP Service Requested Leader to the State DCN NO. Item Numbers Comten Port No. (out bldgs, and dedicated lines only) Type of Service Requested: Exchange-from Make ___ ID/Serla Relocate-Make_ Other (describe in Section 5) System application access (check or signoff where applicable): RUFFING. _OTHER_ *CAMS **DESIST .**4C "SAFE "SPECIAL CENTER **Requires signoff by Systems Approval Officer Section 5: Additional Information SEE ATTARCED MEMO Classify as Appropriate WHITE-OIT/ASB GREEN-OIT/CEIB CANARY-OL PINX-REQUESTORS COPY GOLDENROD-REQUESTORS COMEBACK

STATE

FBIS-2516/88 27 April 1988

MEMORANDUM FOR: Chief, Communication Engineering Division, OIT

FROM: Acting Chief, Engineering Support Group, FBIS

SUBJECT: Reconfiguration of MicroVax Circuits to Dial-up Mode

1. Within the PBIS has a non-secure MicroVax computer with 15 terminals located throughout Each terminal communicates with the MicroVax through a pair of ITE 12s (Integrated Telephone Equipment), which are connected to the PBX. Each pair of ITEs is configured to support a continuous, asynchronous, 9600 bits/second data circuit.

STAT STAT

- 2. The purpose of this letter is to request that 12 of these circuits be reconfigured to support the following operations:
 - a. Non-secure FBIS terminals in Reston can dial any of 12 MicroVax communication ports when configured as:

Full Duplex
Asynchronous
9,600 Bits/Second
1 Start Bit
1 Stop Bit
8 Data Bits
No Parity
Xon/Xoff Flow Control

b. Each of 12 MicroVax ports can automatically answer incoming calls.

FBIS-2516/88

Subject: Reconfiguration of MicroVax Circuits to Dial-up Mode

c. The EIA-232 cable pin-out configurations are:

<u>Pin</u>	<u>Function</u>	<u>Pin</u>	Function
1 -	Chassis Ground	8 ~	Data Carrier Detect
2 -	Transmit Data	12 -	Speed Indicator
3 -	Receive Data	13 -	Secondary Clear to Send
4 -	Request to Send	19 -	Secondary Request to Send
5 -	Clear to Send	20 -	Data Terminal Ready
6 -	Data Set Ready	22 -	Ring Indicator
7 -	Signal Ground	23 -	Speed Selector

- d. Each MicroVax terminal operator has voice and data capability.
- 3. The jack numbers and/or telephone extensions to be supported by this reconfiguration change are listed below. An asterisk (*) indicates that a terminal needs to be relocated to that jack number (all relocation requests have been submitted to OIT on Form 4340s).

DATA TERMINAL

BS3-130

BS3-125

BN3-036

BN3-037

		_ , ,	_			_	
	Jack	Telephone	Room	Jack	Telephone	Room	
	<u>Number</u>	<u>Extension</u>	<u>Number</u>	_Number_	<u>Extension</u>	Number	
*	BS1-092	N/A	1S18A	N/A		3N18	STAT
*	BS1-093	N/A	H	N/A		11	
	BS2-085		2S16	N/A		†1	STAT
	BS2-052		11	N/A		11	
	BS2-044		11	N/A		rı	
	BS2-081		"	N/A		11	
*	BS2-023		2S46B	N/A		11	
*	BS2-036		2S46A	N/A		11	

N/A

N/A

N/A

N/A

MICROVAX

3S18

**


3N48 ·

Declassified in Part - Sanitized Copy Approved for Release 2013/06/25 : CIA-RDP91-01355R000300170008-1

FBIS-2516/88

Subject: Reconfiguration of MicroVax Circuits to Dial-up Mode

- 4. The locations of the 12 terminals have been identified on Attachments A, B, C, D, and B.
- 5. FBIS recognizes that such a request would normally be submitted to the Customer Support Group. In this case, the Communication Engineering Division has been requested to support this project because its contractor, CONTEL, is already modifying these data circuits to meet shielded enclosure requirements for room 3N18. FBIS desires to minimize confusion about the circuit configuration by having the two projects addressed by the same work force.



Attachments

FBIS-2516/88

(20APR1988)

SUBJECT: Reconfiguration of MicroVax Circuits to Dial-up Mode

		•					
Distribution:							
Original -	C/CED						
	C/ADMIN						
1 -	C/LOGS						
1 -	C/HED						
	HED Staff						
1 -	C/EB						
	C/ADD						
	ADD Staff	-					
1 -		COTR					
1 -		. ADD					
<u> </u>	CRD/OTT	ř					

GE/SES

GE/SES

DS&T/FBIS/ESG/ADD/SES:

1 - CSG/OIT,

1 - ADD Chrono
1 - ESG Chrono
1 - FBIS Registry
1 - GE/SES Chrono
1 - Originator

STAT

STAT

STAT

STAT

-4-

